



Original post set 1820 by Hendricks with witnesses: 30" beech S 61 W 26 links, 8" dagwood N 50 E 22 links per Marion County Atlas pg. 15. Records indicate no monuments or witnesses per Lawrence Township Legal Survey Book pg. 45. Corner computed by Kent called 5/8" rebar with capset 7-25-78. Green 4-28-83 called 5/8" steel rebar. Plat of 4-16-5 prepared by Schneider Engineering 9-1981. Corner falls 2.18'S and 14.72'E of the corner previously set and tied in 7-1978. Excavated by Kiste 3-10-94 and 5/8" rebar found at surface. Harrison set. Re-tied 11-1-95 by Wilcoxen. Re-tied 5-10-2000 by Wilcoxen.

HC 650402

REF.	DISTANCE	DESCRIPTION
1.	61.50	SW corner of siding for ADDRESS 6108
2.	9.71	Railroad spike NW 24" hackberry 8"up
3.	6.18	Railroad spike SW 20" hackberry 8"up
4.	32.74	Railroad spike E twin hackberry 8"up
5.	9'+/-	Due S to plastic fence line
6.	11.65	NE corner of plastic fence post
7.	22.70	Railroad spike N 24" hackberry 12"up
8.	4'+/-	Due W to plastic fence line